

EvoCare<sup>®</sup>



# FETAL Transducers

Compatible Ultrasound,  
Toco Transducers and  
Repair Parts

Toco Transducers

8 foot cable



Ultrasound Transducers

8 foot cable




Repair Cables


Easy installation, big savings




### AEON US Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
A100B				<b>EAE-USB</b>




### AEON TOCO Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
A100B				<b>EAE-TOB</b>




### BIOLIGHT US / TOCO Transducer combined

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
F80 / F90				<b>EBLT-U/T</b>


### BIONICS US Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
IFM500				<b>EIFM-500US</b>
BFM800				<b>EBFM-800US</b>
BFM900 / 900L				<b>EBFM-900US</b>


**BIONICS TOCO Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
IFM500				<b>EIFM-500TOCO</b>
BFM800				<b>EBFM-800TOCO</b>
BFM900 / 900L				<b>EBFM-900TOCO</b>


**BESTMAN US Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
BFM720 / 700M / 700E / PLUS				<b>EBFM-700US</b>


**BESTMAN TOCO Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
BFM720 / 700M / 700E / PLUS				<b>EBFM-700TOCO</b>



**BISTOS US Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
BFM720 / 700M / 700E / PLUS				<b>EBIS-300US</b>

**BISTOS TOCO Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
BT300				<b>EBIS-300TOCO</b>


**BIONET US Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
FC-700				<b>EBIO-700US</b>
FC-1400				<b>EBIO-1400US</b>


**BIONET TOCO Transducer**

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
BT300				<b>EBIO-700TOCO</b>
FC-1400				<b>EBIO-1400TOCO</b>


### CONTEC US / TOCO 3-IN-1 Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
CMS800G				<b>ECON-800G</b>


### COMEN US Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
STAR 5000C /D /E			TEVEIK	<b>ECOM-5US</b>


### COMEN TOCO Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
STAR 5000C /D / E				<b>ECOM-5TOCO</b>


### COMEN US / TOCO 3-IN-1 Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
STAR 5000B				<b>ECOM-5B3</b>



### COROMETRICS Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Corometrics Nautilus 5700LAX Corometrics 116, 118, 120, 128, 129, 145, 150, 151, 155, 170, 171, 172, 173, 174, 250, 259 and 340 monitors		<b>EVU300-10</b>	5700LAX	<b>TFCU201</b>


## COROMETRICS Toco Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Corometrics Nautilus 2264LAX for Corometrics 116, 118, 120, 128, 129, 150, 151, 155, 170, 171, 172, 173, 174, 250, 259 and 340 monitors		<b>EUFT300-10</b>	2264LAX	<b>TFCT202</b>


## COROMETRICS Transducer Repair Cable

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Use this compatible cable to repair the GE Corometrics 5700AAX ultrasound transducer		<b>EX-US-CR2</b>		<b>TFCU201-CR</b>
Use this compatible cable to repair the GE Corometrics 2264AAX toco transducer		<b>EX-TC-CR1</b>		<b>TFCT202-CR</b>

## EDAN Ultrasound Transducer


Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
F2 /3 /6 /9				<b>EEDAN-US</b>

## EDAN Toco Transducer


Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
F2 / 3 / 6/9				<b>EEDAN-TOCO</b>

## FETALCARE – SEE BIONET


## HWATIME US / TOCO 3-IN-1 Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
T10				<b>EHWA-T10</b>



### MARS Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
MARS B SERIES MARS K SERIES			ORIGINAL	<b>EVMARS-US</b>


### MARS Toco Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
MARS B SERIES MARS K SERIES			ORIGINAL	<b>EVMARS-TOCO</b>


### Oxford Huntleigh Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Oxford Sonicaid Team Duo 1.5MHz		<b>E8031040</b>	8400-6919	<b>EHUN-US1.5</b>
Oxford Sonicaid Team Duo 2MHz		<b>E8031039</b>	8400-6920	<b>EHUN-US2.0</b>



### Oxford Huntleigh Toco Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Oxford Sonicaid Team Duo		<b>E8032026</b>	8400-6921	<b>EHUN-TOCO</b>



### Philips Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Model 1350 and Series 50 monitors		<b>EUFU200-20</b>	M1356A	<b>ETFHU101</b>



### Philips Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
HP 8040A and 8041A monitors		<b>EUFU200-10</b>	15245A	<b>ETFHU102</b>
AVELON – ORIGINAL			M2736A	<b>EM2736A</b>






### Philips Toco Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Model 1350 and Series 50 monitors		<b>EUFT200-20</b>	M1355A	<b>ETFHT102</b>
AVALON - ORIGINAL			M2734A	<b>EM2734A</b>


### Philips AVALON Transducer Repairs

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
AVALON US and TOCO local repair and tested  New covers / new cables				<b>EVO-AV-USR</b>  <b>EVO-AV-TR</b>
AVALON US and TOCO  SERVICE EXCHANGE ( overseas repair )				<b>EVO-AV-USEX</b>  <b>EVO-AV-TEX</b>


### Philips Transducer Repair Cable

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
Use this cable to repair Philips M1356A ultrasound transducers		<b>EX-US-HP1</b>		<b>EV-U-HP1</b>
Use this cable to repair Philips M1355A TOCO transducers		<b>EX-TC-HP1</b>		<b>EV-T-HP1</b>
Use this cable to repair Philips 15245A US transducers		<b>EX-US-HP2</b>		<b>EV-U-HP2</b>
Use this cable to repair the Philips 15248A TOCO transducer		<b>EX-TC-HP2</b>		<b>EV-T-HP2</b>
Use this cable to repair the Philips M2736A/ M2734A US and TOCO transducer		<b>EX-US/TC-HP3</b>		<b>EV-U/T-HP3</b>

### SUNRAY Ultrasound Transducer

Models	Connector	Part Number	ORIGINAL OEM #	EVOTEC OEM
SRF 618K9, 618B5 , 618B6				<b>ESUN-US</b>

### SUNRAY Toco Transducer

Models	Connector	Variant SKU	ORIGINAL OEM #	EVOTEC OEM
SRF 618K9, 618B5 , 618B6				<b>ESUN-TOCO</b>

**UNICARE** see MARS

LEFT BLANK